



123 Main St Dallas TX 76543

COURTESY OF

Repair Pricer LLC

PREPARED BY:

Paul Jackson Sent: Tue, 12 Mar 2019 16:29

> QUESTIONS? CLICK HERE TO GET HELP



Summary



WHOLE HOME ESTIMATE:

\$9,217

Prepared for: Mr Eric Sample | Prepared by: Paul Jackson.



Item	Pg Action	Price
MASON		
Foundation wall imperfections	0 Beam patch at exposed cables or rebar, cracks and corner pops	\$
	Sub-Total (Mason)	\$
CARPENTER/HANDYMAN		
Doors need adjusting and servicing	8 Adjust noted doors throughout property including weatherstripping and door stops	
Access ladder needs servicing	11 Service pull down stairs for correct nails and lag bolts, repair, adjust for correct seal and insulation	\$
	Sub-Total (Carpenter/Handyman)	\$
ELECTRICIAN		
Double lugging	8 Re wire so as not to have two wires going to one breaker	9
Change out Federal Pacific panel	8 Remove federal pacific panel and install a panel up to code	
Outlets or switches with deficiencies	16 Repair noted outlets and switches for deficiencies and plates	5
	Sub-Total (Electrician)	\$3
PAINTER/DRYWALL		
Exterior caulk and seal is missing in some areas	8 Caulk penetrations and openings, windows, electrical fixtures, piping, vents, seams at siding and trim	\$
	Sub-Total (Painter/DryWall)	S
PLUMBER		
Sediment or gas drip leg needed	5 Install gas drip leg at water heater	9
Gas flex pipe used at Heater	7 Change to iron pipe through the opening to improve safety	\$
	Sub-Total (Plumber)	ŝ
НУАС		
No sediment trap	8 Install sediment trap at gas supply in noted areas	5
No sediment trap	8 Install sediment trap at gas supply in noted areas	\$
Coils are dirty or damaged on AC	8 Service call to clean and repair coils and improve air flow, install insulation where needed	

Prepared for: Mr Eric Sample | Prepared by: Paul Jackson.



ŧ Item	Pg Action	Price
LANDSCAPER		
3 Tiles are cracked or missing	8 Repair and install noted areas	\$34
4 Lot does not facilitate proper drainage	12 Dig swales into lot to drain water and level out high or low soil levels	\$59
	Sub-Total (Landscaper)	\$93
CHIMNEY		
5 Fireplace damper missing bracket	14 Install Clamp on damper for safety	\$12
6 Chimney cleaning recommended	14 Full chimney sweep	\$34
	Sub-Total (Chimney)	\$47
APPLIANCE		
7 No antisiphon loop at drain line for dishwasher	6 Install anti siphon or vacuum break	\$8
8 Dishwasher needs servicing	6 Service noted items	\$10
	Sub-Total (Appliance)	\$19
GUTTERS		
9 Leave or debris in the gutters and downspouts	12 Clean out gutters and downspouts, general service and repair	\$32
0 Downspouts extensions needed	12 Install extension to divert water	\$18
	Sub-Total (Gutters)	\$50
VENTS		
1 Insufficient attic ventilation	11 Install more vents	\$64
	Sub-Total (Vents)	\$64
FURTHER ACTION REQUIRED		
2 Structural engineering inspection	2 Inspect structural support and recommend repairs	\$78
3 Intrusive stucco inspection	2 Remove and drill sections of stucco to test moisture levels	\$1,18
4 Hydrostatic test of sewer line	5 Inspect drain system	\$27
	Sub-Total (Further Action Required)	\$2,24
	Total	\$10,37

Thank you for choosing Repair Pricer

About Repair Pricer

Repair Pricer is the industry standard for converting inspection reports into accurate repair estimates during the complex home purchasing process, enabling all parties to act quickly and confidently during a critical period. Repair Pricer saves time and reduces stress for everyone when it matters most. To learn more about Repair Pricer, visit www.repairpricer.com



It is important you understand that the service provided by RepairPricer.com is purely for estimation and negotiation purposes. We do not guarantee that the prices we estimate for repairs on your report are the same that you will end up paying for that specific repair. Our pricing is based on the average cost for a similar repair in your area, and due to unknown factors or underlying issues that we are not privvy to, actual repair cost may be substantially higher.

> QUESTIONS? CLICK HERE TO GET HELP