

COURTESY OF


Repair Pricer LLC

PREPARED BY:



Summary





WHOLE HOME ESTIMATE:

\$9,217



#	Item	Pg	Action	Price		
	MASON	O. Berneralde de		\$5.40		
1	Foundation wall imperfections	0 Beam patch at ex	posed cables or rebar, cracks and corner pops	\$542		
	Sub-Total (Mason)					
	CARPENTER/HANDYMAN					
	Doors need adjusting and servicing		s throughout property including weatherstripping and door stops	\$109		
3	Access ladder needs servicing	11 Service pull down	stairs for correct nails and lag bolts, repair, adjust for correct seal and insulation	\$123		
		Sub-Total (Carpe	nter/Handyman)	\$232		
		Sub-Total (Carpe	men namy many	Ψ 2 32		
	ELECTRICIAN					
4	Double lugging	8 Re wire so as not	to have two wires going to one breaker	\$148		
5	Change out Federal Pacific panel	8 Remove federal p	acific panel and install a panel up to code	\$2,958		
6	Outlets or switches with deficiencies	16 Repair noted outle	ets and switches for deficiencies and plates	\$118		
		Sub-Total (Electi	ician)	\$3,224		
		oub rotal (Liceti	iolan,	ψ0,224		
	PAINTER/DRYWALL					
7	Exterior caulk and seal is missing in some areas	8 Caulk penetration	s and openings, windows, electrical fixtures, piping, vents, seams at siding and trim	\$345		
		Sub-Total (Paint	or/DestWall)	\$345		
		Sub-Total (Failt	ni jiyanij	-		
	PLUMBER					
8	Sediment or gas drip leg needed	5 Install gas drip leg	at water heater	\$198		
9	Gas flex pipe used at Heater	7 Change to iron pi	e through the opening to improve safety	\$227		
		Sub-Total (Plum	ner)	\$425		
		odb Total (Tidill		Q423		
	HVAC					
10	No sediment trap	8 Install sediment tr	ap at gas supply in noted areas	\$199		
11	No sediment trap	8 Install sediment tr	ap at gas supply in noted areas	\$199		
12	Coils are dirty or damaged on AC	8 Service call to cle	an and repair coils and improve air flow, install insulation where needed	\$205		
		Sub-Total (HVAC		\$603		
		Sub-Total (HVAC	,	\$603		
1				1		

03-12-2019



#	Item	Pg	Action	Price
	LANDSCAPER			
13	Tiles are cracked or missing	8 Repair and install noted areas		\$345
14	Lot does not facilitate proper drainage	12 Dig swales into lot to o	drain water and level out high or low soil levels	\$592
		Sub-Total (Landscap	per)	\$937
	CHIMNEY			
15	Fireplace damper missing bracket	14 Install Clamp on damp	per for safety	\$128
16	Chimney cleaning recommended	14 Full chimney sweep		\$345
		Sub-Total (Chimney)		\$473
	APPLIANCE			
17	No antisiphon loop at drain line for dishwasher	6 Install anti siphon or v	racuum break	\$89
	Dishwasher needs servicing	6 Service noted items		\$109
	•			
		Sub-Total (Appliance	e)	\$198
	GUTTERS			****
	Leave or debris in the gutters and downspouts Downspouts extensions needed	12 Clean out gutters and 12 Install extension to div	downspouts, general service and repair	\$322 \$187
20	Downspouls extensions needed	12 Install extension to div	reit water	\$107
		Sub-Total (Gutters)		\$509
	VENTS			
21	Insufficient attic ventilation	11 Install more vents		\$641
		Sub-Total (Vents)		\$641
	FURTHER ACTION REQUIRED			
22	FURTHER ACTION REQUIRED Structural engineering inspection	2. Inencet etruetural euro	port and recommend repairs	\$789
	Intrusive stucco inspection		ions of stucco to test moisture levels	\$1,183
	Hydrostatic test of sewer line	5 Inspect drain system	ions of stacco to test moisture levels	\$276
		Sub-Total (Further A	ction Required)	\$2,248
		Total		\$10,377

Thank you for choosing Repair Pricer

About Repair Pricer

Repair Pricer is the industry standard for converting inspection reports into accurate repair estimates during the complex home purchasing process, enabling all parties to act quickly and confidently during a critical period. Repair Pricer saves time and reduces stress for everyone when it matters most. To learn more about Repair Pricer, visit www.repairpricer.com



It is important you understand that the service provided by RepairPricer.com is purely for estimation and negotiation purposes. We do not guarantee that the prices we estimate for repairs on your report are the same that you will enurp paying for that specific repair. Our pricing is based on the average cost for a similar repair in your area, and due to unknown factors or underlying issues that we are not privvy to, actual repair cost may be substantially higher.